


DriveMaster 2010 Dialog Bar

DEV 1	LBA 13EC	LEN 1	SEND 00 00 00 00 00 <-- Prev	RECV: 04 00 00 00 00 <-- Prev	M S F 0 0 0 5
SStatus: 00000113	SError: 00000000	NO_DATA 00 00 00 00 00 10 EC	-- Rcnt --> 04 31 ED 13 00 F0 59	START: 0 0 0 00 00 00 00 00 00	END: 0 0 0 00 00 00 00 00 00
HBA Max Slot: 32	Dev. Max Slot: 32	QDepth: 0	CstmXferBytes: 7	1	7
Device Type: ATA	Serial NO. SOM2J10LB00440	Model NO. SAMSUNG	HM08HHI	Firmware Rev. CD100-02	Capacity: 80 GB



DEV 1	LBA 13EC	LEN 1	SEND 00 00 00 00 00 <-- Prev	RECV: 04 00 00 00 00 <-- Prev	M S F 0 0 0 5
SStatus: 00000113	SError: 00000000	NO_DATA 00 00 00 00 00 10 EC	-- Rcnt --> 04 31 ED 13 00 F0 59	START: 0 0 0 00 00 00 00 00 00	END: 0 0 0 00 00 00 00 00 00
HBA Max Slot: 32	Dev. Max Slot: 32	QDepth: 0	CstmXferBytes: 7	1	7
Device Type: ATA	Serial NO. SOM2J10LB00440	Model NO. SAMSUNG	HM08HHI	Firmware Rev. CD100-02	Capacity: 80 GB

